

November 1, 2004

Steve Wolfe
Fiber Utility Process Leader
Georgia Pacific Camas Mill
401 NE Adams
Camas, WA 98607

Dear Mr. Wolfe:

Subject: 2004 Operator Qualification Inspection

On October 4th and 5th, 2004, Pipeline Safety staff (Staff) representing the Washington Utilities and Transportation Commission, conducted an inspection of Georgia Pacific Camas Mill (GP) Operator Qualification Program (OQ).

The review of GP's OQ Plan, practices, and documentation did not identify any violations of CFR 49, Part 192 Subpart N. It is not to be assumed that this inspection detected all apparent code violations at this time. It is incumbent upon the operator to review its operations to determine whether or not there are other areas of non-compliance.

Staff appreciates Mr. Roy Roger and Mr. Mike Fjermestad's cooperation. Please contact Patti Johnson at (360) 664-1266 or (360) 870-4915 for technical assistance or questions.

Sincerely,

Alan E. Rathbun
Pipeline Safety Director

cc: Roy Roger
Greg Collins

The Washington Utilities and Transportation Commission (Commission) has the authority to enforce the minimum safety regulations per Chapter 480-93 of the Washington Administrative Code (WAC) pertaining to the construction, maintenance and operation of pipelines transporting natural gas in the state of Washington. In addition, the Commission adopts the Code of Federal Regulations (CFR) Title 49, Part 191 and 192.